


FIG.5A



F I G. 5B

Case in which almost no motion verctor is present




FIG. 6A

Case in which motion vectors in the same direction/size are distributed over the entire frame




FIG.6B

Case in which a motion vector partially located in frame




FIG.6C

Case in which motion vectors are distributed in a radiation manner in frame




FIG.6D

Case in which there exists a larger number of motion vectors in a frame, and directions are not uniform







FIG. 6E



icto-block iii willich a mosquito noise is likely to occur










FIG.8A





Mode	Motion vector	Texture
------	------------------	---------

FIG. 12

